

2023 KZ RV Durango D311BHD

\$59,900



Item

Item URL: <https://www.rvpostings.com/502210> **Item reference number**
#502210

Dealer

Rte. 125 RV u0026 Marine, Inc.
Phone: 8883661471
Email: import238662@rvpostings.com

Quick info

0 mi

Details

Item type: For sale
Posted on : 03/28/2024

Description

2023 KZ RV Durango D311BHDFull-Profile Luxury Fifth WheelsDurango offers all the upscale staples at an affordable price. Durango is approved for full-time living with an all-weather insulation package.Features may include:Off-the-grid solar package (optional)Modern farmhouse cabinetryKing size bed standardSmart TVs30" Convection microwave + 24" oven with four burner rangeOptions: F/S Table & 4 Chairs IPO Dinette18CF House Residential Refer IPO 12CF2nd 15,000 BTU A/C Ducted2nd LED Lighted Power AwningPower Vent Fan - Bathroom

Basic information

Year: 2023
Stock Number: C-11502
VIN Number: rte125rv&marine-5378-C-11502

Item address

[343 Gonic Rd. 3839, Rochester, New Hampshire, United States](#)

2023 KZ RV Durango D311BHD

\$59,900

Item images



D311BHD



Pre-Owned Peace of Mind Guarantee*

With over 50 years of experience in our service department, the KZ RV & Marine believes purchasing a pre-owned RV should come with peace of mind. That's why every pre-owned and new RV we sell comes with not only our industry leading inspection process but a full demonstration of the camper. A buyer not only will see all of the RV's systems functioning but will learn how to use and operate each system.

EXTERIOR INSPECTIONS

The following exterior features will be functioning properly on the day of delivery.

- Slide outs (operated, no leaks)
- Roof (inspected, no leaks)
- Tires, brakes, axles, and bearings
- Outside marker lights
- Turn signals
- Proper Safety check performed and passed
- Exterior appliances
- Entry steps
- Heating, venting fabric not torn and free of holes
- All heating systems (if installed)
- Charge jack
- Breakaway switch
- Stabilizer jacks

INTERIOR INSPECTIONS

Includes all interior and exterior inspections plus additional manufacturer specific inspections.

- Suspension & drivetrain inspected
- Inverter (if installed) & house batteries functioning
- State inspection performed and passed
- Windshield not cracked
- Windows functioning & in good condition
- Brake system works properly, pads, brake lines condition all inspected
- Unit has been road tested to ensure safe driving and dashboard is functioning properly.

INTERIOR INSPECTIONS

The following appliances and detectors will be functioning properly on the day of delivery.

- Refrigerator
- Water heater
- Furnace
- A/C
- Range
- Oven
- Microwave
- Smoke detector
- Propane detector
- Carbon monoxide detector
- Fire extinguisher installed
- Generator (if equipped)
- Churning system
- Sewage system
- Water pump



*See website for complete details.